6130.3700 AIR POLLUTION.

Subpart 1. Goal. Mining shall be managed to control avoidable dust.

Subp. 2. **Requirement.** Avoidable dust shall be controlled by techniques such as water spray, chemical binders, anchored mulches, vegetation, and enclosure and containment.

Statutory Authority: MS s 93.47

Published Electronically: June 11, 2008