

4727.0860 PLACEMENT OF LICENSE NUMBER AND DECALS.

Subpart 1. **License number display.** Before beginning exploratory boring, the licensee must place the explorer's license number in a conspicuous location. The license number must be attached to both sides of each drilling machine or hoist or, if the licensee does not own the drilling machine or hoist, the license number must be attached to a portable sign that is displayed near the exploratory boring while work is being conducted. The license number figures must be at least three inches high and 1-1/2 inches wide and must be in a contrasting color to the rest of the machine, hoist, or sign.

Subp. 2. **Registration decal display.** Before beginning exploratory boring, the person registering the drilling machine or hoist is responsible for affixing the decals issued by the commissioner to the drilling machine or hoist. The licensee may not conduct exploratory boring unless the drilling machine or hoist is registered with the commissioner and has current decals issued by the commissioner.

Statutory Authority: *MS s 103I.101*

History: *28 SR 147*

Published Electronically: *September 15, 2003*