

**4731.6270 REPORTS.**

Subpart 1. **Required reports.** If not reported under other parts of this chapter, a licensee must report the following events:

- A. source stuck in an unshielded position;
- B. any fire or explosion in a radiation room;
- C. damage to the source racks;
- D. failure of the cable or drive mechanism used to move the source racks;
- E. inoperability of the access control system;
- F. detection of radiation source by the product exit monitor;
- G. detection of radioactive contamination attributable to licensed radioactive material;
- H. structural damage to the pool liner or walls;
- I. abnormal water loss or leakage from the source storage pool; and
- J. pool water conductivity exceeding 100 microsiemens per centimeter.

Subp. 2. **Content.** A report under subpart 1 must include a telephone report within 24 hours according to part 4731.3110, subpart 3, item A, and a written report within 30 days according to part 4731.3110, subpart 3, item B.

**Statutory Authority:** *MS s 144.1202; 144.1203*

**History:** *29 SR 755*

**Published Electronically:** *March 12, 2009*