

**7017.1215 INCORPORATION BY REFERENCE; QUALITY ASSURANCE AND CONTROL REQUIREMENTS FOR COMS.**

For quality assurance and control requirements for COMS, the facility owner or operator must conduct quality assurance and quality control as specified in Procedure 3 - Quality Assurance Requirements for Continuous Opacity Monitoring Systems at Stationary Sources, Code of Federal Regulations, title 40, part 60, Appendix F, as amended, which is incorporated by reference.

**Statutory Authority:** *MS s 115.03; 116.07*

**History:** *41 SR 763; 44 SR 1030*

**Published Electronically:** *April 16, 2020*