REVISOR

4715.0805 PUSH-ON JOINTS.

Subpart 1. Water service joints. Push-on joints may be used in cast iron and ductile iron water service pipe located underground outside the building, and must comply with ANSI-A21.11-85. Lead-tipped gaskets are prohibited.

Subp. 2. Water distribution joints. Removable and nonremovable push-fit fittings that comply with ASSE 1061-2006 may be used in copper pipe water distribution for aboveground installation. The installer must be certified by the manufacturer to install that manufacturer's fitting.

Statutory Authority: MS s 16B.61; 16B.62; 326.37; 326B.106; 326B.121; 326B.43

History: 15 SR 76; 19 SR 590; L 2007 c 140 art 4 s 61; art 6 s 15; art 13 s 4; 33 SR 2042

Published Electronically: May 14, 2012