

**4725.3550 WELL LABEL.**

Subpart 1. **Label required.** A person who has constructed a well must attach a well identification label provided by the commissioner to the well before placing the well into service unless the well is sealed within 90 days of construction.

Subp. 2. **Attachment.** The well identification label must be attached to the well casing in a visible location using a stainless steel clamp, band, or strap. Alternatively, the label may be attached to a concrete pump base or pedestal, or at-grade well vault using screws or fasteners.

Subp. 3. **Maintenance.** The property owner must maintain the well identification label in a readable condition.

Subp. 4. **Removal; reattachment.** The well identification label must not be removed except to work on the well. On completing work, the label must be reattached.

**Statutory Authority:** *MS s 103I.101; 103I.111; 103I.205; 103I.221; 103I.301; 103I.401; 103I.451; 103I.501; 103I.525; 103I.531; 103I.535; 103I.541; 103I.621; 144.05; 144.12; 144.383; 157.04; 157.08; 157.09; 157.13*

**History:** *17 SR 2773; 33 SR 211*

**Published Electronically:** *September 2, 2008*