## 4731.4620 REQUIREMENTS FOR OPERATORS OF FUSION IMAGING DEVICES.

Subpart 1. **Accreditation required.** When a unit is operated as a fusion imaging device or in a dual mode such as a SPECT/CT or PET/CT device, the operator must be accredited or must meet the requirements in chapter 4732.

Subp. 2. **Diagnostic CT imaging device.** When the unit is operated as a stand-alone diagnostic CT imaging device, the operator must meet the requirements in chapter 4732.

**Statutory Authority:** MS s 144.1202; 144.1203

**History:** 36 SR 74

Published Electronically: August 15, 2011