

7011.1630 EXCEPTIONS.

Shutdowns and breakdowns of control equipment at any sulfuric acid production unit shall be governed by the provisions of part 7019.1000.

Statutory Authority: *MS s 116.07*

History: *18 SR 614; 18 SR 1412*

Published Electronically: *February 25, 2008*