

4725.1840 UNSUCCESSFUL COMPLETION OF A WELL OR BORING.

If a water-supply well, monitoring well, dewatering well, bored geothermal heat exchanger, or elevator boring for which a notification or permit has been filed is unsuccessful, a new well or boring may be constructed for the same owner on the same property within 18 months of notification or permit approval, without submitting a new construction fee, notification, or permit application if:

A. the construction and depth of the new well or boring is not substantially different from the initial well or boring;

B. the person installing the well or boring submits an amended well and boring construction record; and

C. the unsuccessful well or boring is sealed according to this chapter and a sealing record is submitted.

Statutory Authority: *MS s 103I.101; 103I.111; 103I.205; 103I.221; 103I.301; 103I.401; 103I.451; 103I.501; 103I.525; 103I.531; 103I.535; 103I.541; 103I.621*

History: *15 SR 78; 33 SR 211; L 2013 c 108 art 12 s 108; L 2014 c 275 art 1 s 136*

Published Electronically: *October 10, 2014*